

PUBLIC WORKS DIVISION NASHIK

Outward No. DB/382/2022
Office of The Executive Engineer
P.W.Division Nashik
E-mail nashik.ee@mahapwd.com
Date: 22/7/2022


प्रति,

Principal
St. Thomas Malankara catholic School,
G.No. 100+101, Pimpalgaon, Wasali Gaon Road,
Trimbak Vidyamandir Nashik,
Tal.Dist- Nashik – 422213.

Subject:- Request to visit and conduct the inspection of school building and issue Building Safety Certificate for the same

Reference:- 1. With reference to your letter date on 02/05/2022
2. Report submitted by Subdivisional officer P.W, South Subdivision Nashik letter no. 1398/2022 Date. 18/07/2022.

With reference to your letter dated 02/05/2022 for conducting the inspection and issue of the Building Safety Certificate to St. Thomas Malankara catholic School,G.No. 100+101, Pimpalgaon, Wasali Gaon Road, Trimbak Vidyamandir Nashik, Tal.Dist- Nashik – 422213, we are pleased to inform you that as per the physical inspection conducted by our official on 02/06/2022 at St. Thomas Malankara catholic School,G.No. 100+101, Pimpalgaon, Wasali Gaon Road, Trimbak Vidyamandir Nashik Tal.Dist- Nashik, We are awarding the **Building Safety Certificate** as per the prescribed format to St. Thomas Malankara catholic School,G.No. 100+101, Pimpalgaon, Wasali Gaon Road, Trimbak Vidyamandir Nashik, Tal. Dist- Nashik. The copy of the certificate is attached herewith.


Executive Engineer
Public Works Division Nashik

Copy to: Subdivisional officer P.W, South Subdivision Nashik for information.


BUILDING SAFETY CERTIFICATE

This is to certified that this office inspected the building of **St.Thomas Malankara Catholic School,Gat No.100+101 Pimpalgaon Wasali Road Trimbak Vidyamandir Nashik Taluka and District , Nashik** and found that building is RCC frame structure having 2544.12 sq.mtr.(G+2 storie) Building is constructed for school education purpose with sufficient facilities like Laboratory, Sanitation, Lighting, Ventilation, First aid facility, safe drinking water, playground, Ramp at Entrance, security system and emergency exit etc. The School Building owned by **St.Thomas Malankara Catholic School** As per Drawings of building provided by school and stability certificate for school building issued form Structural Consultant Mathews P. Varghese the above mentioned owners/occupants have complied with the Building Bye Laws in accordance with rule of state/UT, and incorporate the provisions of building safety as specified in National Building code 2005 and as amended thereafter and has been verified by the officer of this office on 2/06/2022 in the presence of Manager Mr. Justin John & Principal Neelam Chokhar nashik and that the said above building/premises is safe and fit for running School with effect from 2/6/2022 for a period of 1 year in accordance with rules.

This Certificate is issued on request letter of Principal, **St.Thomas Malankara Catholic School,Gat No.100+101 Pimpalgaon Wasali Road Trimbak Vidyamandir , Nashik** for CBSE board affiliation purpose.

Outword no. **DB/382/2022**


Office of the executive Engineer
P. W.Division, Nashik.


Sub Divisional Officer
P.W.(south) Sub division

Date: **22/07/2022**

Nashik
Counter Sign

St.Thomas Malankara Catholic School,
Gat No.100+101,
Behind Metro Zone, SN. NO. 30/2,
Pimpalgaon Wasali Road
Trimbak Vidyamandir Nashik-422213


Executive Engineer
P.W. Division Nashik
Executive Engineer
Public Works Division, Nashik